

Report Details

Address:	Requested by:
Sample, Sample	Sample
Grid Reference:	Date:
E: 123456 N: 123456	13/12/2023
Report Reference:	Report ID:
Sample	300944

Professional Opinion

 No further recommendations This page should always be read in conjunction with the full report. The Professional Opinion indicates the potential risks and any other potential issues associated with the property. The results should be disclosed to client and/or lender and/or insurer as appropriate. A 'Pass' is given if no potential property specific risk has been identified. A 'Pass with Considerations' is given where there are potential hazards in the locality to bear in mind, or if there are features nearby which some clients might consider could affect them. A 'Further Action' is given if there is a potential property specific risk and a further action is advised. In the event of a request to review the Professional Opinion based on additional information, or if there are any technical queries, the professional advisor who ordered the report should contact us at insight-info@dyedurham.com, or call us on 0330 900 7500. 	1.GROUND STABILITY	PASS	EARTH SENSE	Air Quality Index: Now available in our Premium searches
	► No further recommendations		 report. The F and any othe The results shinsurer as appled to the results of the results shinsurer as appled to the results of the results. A 'Pass with potential haz features near them. A 'Further A specific risk at In the event of based on add queries, the p should contain the result of the results of the	build always be read in conjunction with the full Professional Opinion indicates the potential risks or potential issues associated with the property. hould be disclosed to client and/or lender and/or propriate. iven if no potential property specific risk has been Considerations ' is given where there are tards in the locality to bear in mind, or if there are try which some clients might consider could affect Action ' is given if there is a potential property and a further action is advised. of a request to review the Professional Opinion ditional information, or if there are any technical professional advisor who ordered the report ct us at insight-info@dyedurham.com, or call us







Assessed by the:

Subject Site



Environmental **Risk Team**

If you require assistance, please contact your Search Provider or alternatively contact us directly with your Report ID. Tel: 0330 900 7500 | Email: insight-info@dyedurham.com



GROUND STABILITY

1.01 Professional Advice	PASS
1.02 Property Subsidence Assessment - Clay Shrink-Swell	PASS

Shrink-swell refers to a change in soil volume as its moisture content changes. Clay-rich soils can absorb lots of water causing them to swell, the ground to rise and overlying structures to lift. This is known as heave. Heave can occur in wetter weather, or where excess water is introduced into the ground by damaged sewer or water pipes. In prolonged dryer weather, or where nearby trees and shrubs have high water demands, clay soils can become very dry. As a result, the ground shrinks, leading to subsidence. Shrink/swell-prone soils are found extensively across England and Wales, with soil shrinkage accounting for approximately 75% of all instances of subsidence.

The British Geological Survey (BGS) Property Subsidence Assessment dataset is a national assessment of Shrink-Swell susceptibility. As well as soil-type, it factors key environmental drivers such as the proximity of trees and the resilience of the property itself to cope with any movement (e.g. age, foundation depth). This provides a more property-specific assessment of susceptibility to shrink-swell related subsidence than considering geology alone.

The Property Subsidence Assessment data provided by the BGS indicates that the property is classified as having a Non-Plastic hazards score. This indicates the underlying geology is non-plastic and therefore cannot undergo any change in volume and therefore cannot have shrink-swell related subsidence.

1.03 Geohazards | Collapsible Deposits

The British Geological Survey indicates that the property is not within 50 metres of an area where there are likely to be natural deposits with the potential to collapse and cause subsidence damage when saturated and loaded by a building or structure.

1.04 Geohazards | Compressible Ground

The British Geological Survey indicates that the property is not within 50 metres of an area where there may be problems due to compressible ground.

1.05 Geohazards | Running Sand

The British Geological Survey indicates that the property is within 50 metres of an area where there is a very low potential for running sand problems if water table rises or if sandy strata are exposed to water. No special actions required to avoid problems due to running sand.

1.06 Mapped Landslides

The British Geological Survey indicates that the property is not located within 25 metres of an area which has observed landslide features. Please note that these features have not been routinely recorded on geological maps, and so their absence does not indicate that landslides have not occurred or may not occur in the future.

1.07 Landslips/slides | Slope Instability

The British Geological Survey indicates that the property is located on or within 50 metres of an area where slope instability problems are not likely to occur.

1.08 Mining Cheshire Brine Compensation Area

The Coal Authority indicates that the property is not located within 25 metres of a Cheshire Brine Compensation District.

1.09 Mining | Coal Mining

The Coal Authority indicates that the property is not within 25 metres of an area that may be affected by Coal Mining.

Request by: Sample References: Sample Id: 300944 Date: 13/12/2023 Tel: 0330 900 7500 | Email: insight-info@dyedurham.com 2 of 6

PASS

PASS

PASS

PASS

PASS

PASS

PASS

Date: 13/12/2023 3 of 6

References: Sample Id: 300944

The dataset categories analysed in this section are listed below. For more information, please visit our website.

1.14 Natural Cavities & Soluble Rocks

Data from the British Geological Survey and Peter Brett indicates that the property is not within 50 metres of an area where there is localised subsidence or the risk of natural cavities or sink holes occurring naturally.

1.15 Checked Datasets

Professional Advice	Property Subsidence Assessment - Clay Shrink-Swell
Geohazards Collapsible Deposits	Geohazards Compressible Ground
Geohazards Running Sand	Mapped Landslides
Landslips/slides Slope Instability	Mining Cheshire Brine Compensation Area
Mining Coal Mining	Mining Mining Cavities (Non-Coal)
Mining Hazards (Non-Coal)	Modified Ground Artificial Deposits
Modified Ground Historical Analysis	Natural Cavities & Soluble Rocks



1.10 Mining | Mining Cavities (Non-Coal)

Peter Brett Associates indicates that the property is not located within 25 metres of an area that may be affected by non-coal mining cavities.

1.11 Mining | Hazards (Non-Coal)

The British Geological Survey indicates that the property is located within 50 metres of an area where sporadic underground mining of restricted extent may have occurred, potential for difficult ground conditions are unlikely and localised and are at a level where they need not be considered.

The Presence of past underground mining is not known to have occurred. Areas are categorized on the basis that the rock type present are known to have been worked in other areas. Areas therefore have the potential for underground mining but there is little or not evidence of mining activity. It should be noted, however, that there is always the possibility of the existence of other subsurface excavations, such as wells, cess pits, follies, air raid shelters/bunkers and other military structures etc. that could affect surface ground stability but which are outside the scope of this dataset.

1.12 Modified Ground | Artificial Deposits

The British Geological Survey indicates that the property is not located within 25 metres of an area where the surface has been observed to have been significantly modified by human activity, such as spoil heaps or railway cuttings. Please note that these features have not been routinely recorded on geological maps, and so their absence does not indicate that this type of modified ground is not present.

1.13 Modified Ground | Historical Analysis

Analysis of historical maps indicates the property is not located on or within of an area where there may be modified ground.

PASS

PASS

PASS

PASS

PASS



NOTES & GUIDANCE

2.01 Report Notes

METHODOLOGY

This report is a desk study risk assessment, and no site or ground inspection or physical investigation has been carried out. The impacts of the risks addressed in this report are normally measured in terms of quiet enjoyment, saleability, mortgageability, and the value of the property; the risk assessment in this report is provided by Dye & Durham (UK) Limited (formerly Future Climate Info Limited).

The cover page of this report should always be read in conjunction with the full report. The Professional Opinion indicates the potential risks and any other potential issues associated with the property. The results should be disclosed to client and/or lender and/or insurer as appropriate.

A 'Pass' is given if no potential property specific risk has been identified.

A 'Pass with Considerations' is given where there are potential hazards in the locality to bear in mind, or if there are features nearby which some clients might consider could affect them.

A 'Further Action' is given if there is a potential property specific risk and a further action is advised

In the event of a request to review the Professional Opinion based on additional information, or if there are any technical queries, the professional advisor who ordered the report should contact us at insight-info@dyedurham.com, or call us on 0330 900 7500.

2.02 Terms of Use

T&Cs, OUERIES & COMPLAINTS

This report is supplied by Dye & Durham (UK) Limited (formerly Future Climate Info Limited) subject to Terms and Conditions of Business, available at https://futureclimateinfo.com/wp-content/uploads/2023/02/FCI-terms-and-conditions-v0223.pdf. In the event of product and content queries please contact insight-info@dyedurham.com. Our formal complaints procedure can be found at http://www.futureclimateinfo.com/complaints.

2.03 Search Code

CONSUMER INFORMATION

IMPORTANT CONSUMER PROTECTION INFORMATION

This search has been produced by Dye & Durham (UK) Limited (formerly Future Climate Info Limited), Imperium, Imperial Way, Reading, Berkshire, RG2 0TD, Telephone 0330 900 7500, Email: insight-info@dyedurham.com, which is registered with the Property Codes Compliance Board (PCCB) as a subscriber to the Search Code. The PCCB independently monitors how registered search firms maintain compliance with the Code.

The Search Code:

- Provides protection for homebuyers, sellers, estate agents, conveyancers and mortgage lenders who rely on the information included in property search reports undertaken by subscribers on residential and commercial property within the United Kingdom.
- Sets out minimum standards which firms compiling and selling search reports have to meet.
- Promotes the best practice and quality standards within the industry for the benefit of consumers and property professionals. Enables consumers and property professionals to have confidence in firms which subscribe to the code, their products and services.

By giving you this information, the search firm is confirming that they keep to the principles of the Code. This provides important protection for you.

The Code's core principles

Firms which subscribe to the Search Code will:

- display the Search Code logo prominently on their search reports.
- act with integrity and carry out work with due skill, care and diligence
- at all times maintain adequate and appropriate insurance to protect consumers
- conduct business in an honest, fair and professional manner
- handle complaints speedily and fairly

Tel: 0330 900 7500 | Email: insight-info@dyedurham.com

ensure that products and services comply with industry registration rules and standards and relevant laws

Request by: Sample

Date: 13/12/2023 4 of 6



• monitor their compliance with the Code

Complaints

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award compensation of up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Code.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPOs or to the PCCB.

TPOs Contact Details:

The Property Ombudsman scheme, Milford House, 43-55 Milford Street, Salisbury, Wiltshire SP1 2BP Tel: 01722 333306, Fax: 01722 332296, Email: admin@tpos.co.uk, Web: https://www.tpos.co.uk/ You can get more information about the PCCB from www.propertycodes.org.uk

PLEASE ASK YOUR SEARCH PROVIDER IF YOU WOULD LIKE A COPY OF THE SEARCH CODE

2.04 Report Lic	ensing	METHODOLOGY
© Crown copyrigh 2023 Ordnance Su	nt and database rights rvey 100049731	
3. USEFUL CO	DNTACTS	
Local Authority : To Tel: Visit:	onbridge and Malling Borough Council 01732 844 522 http://www.tmbc.gov.uk/	
Environment Agen Tel: Visit: Email:	cy l North Lutra House, Dodd Way, Off Seedlee Ros 08708 506 506 www.environment-agency.gov.uk enquiries@environment-agency.gov.uk	ad, Bamber Bridge, Preston. PR5 8BX
Natural Resources Tel: Visit: Email:	Wales 0300 065 3000 http://naturalresources.wales/ enquiries@naturalresourceswales.gov.uk	
JBA Risk Managem Tel:	ent Ltd 1 Broughton Park, Old Lane North, Brough 01756 799919	hton, Skipton, North Yorkshire. BD23 3FD
	and Wellington House, 133-155 Waterloo Road, Lo	ondon. SE1 8UG
Tel: Visit: Email:	020 7654 8000 https://www.gov.uk/government/organisations/ enquiries@phe.gov.uk	'public-health-england
Public Health Wale Tel: Visit:	es 2 Capital Quarter, Tyndall Street, Cardiff, CF10 4 029 2022 7744 http://phw.nhs.wales/	ŀΒΖ
The Coal Authority Tel: Visit: Email:	Property Search Services 200 Lichfield Lane, Berr 0845 762 6848 www.groundstability.com groundstability@coal.gov.ukss	y Hill, Mansfield, Nottinghamshire. NG18 4RG
Request by: Sample	References: Sample Id: 300944	Date: 13/12/2023



The British Geologio	cal Survey Environmental Research Centre, Keyworth, Nottingham, NG12 5GG
Tel:	0115 936 3143
Visit:	http://www.bgs.ac.uk/
Email:	enquiries@bgs.ac.uk
Ordnance Survey 0	Customer Services Ordnance Survey Adanac Drive Southampton SO16 0AS
Tel:	08456 05 05 05
Visit:	www.ordnancesurvey.co.uk/
Department for Bus	siness, Energy & Industrial Strategy 1 Victoria Street London SW1H 0ET
Tel:	020 7215 5000
Email:	enquiries@beis.gov.uk
HomeProtect Hom	neProtect, PO Box 1124, Kingston upon Thames, KT1 1XT
Tel:	0330 660 3600
Visit:	www.homeprotect.co.uk/floodcover
Email:	floodcover@homeprotect.co.uk

S